

4020 Miriam Ave. Bismarck, ND 58501

(701) 224-1026

** Reprint **

Invoice: 280850020

Date / Hour: 3/26/2018 10:47:35AM

Repair Order: 243630 Customer: 01784 Branch: Bismarck Total Invoice: \$37,744.29 ***COD***

Page 1 of 7

Bill To: WAYNE TRANSPORTS

COD INVOICES ONLY

FOR DRIVERS OF CUSTOMER ROSEMOUNT, MN 55068

Ship To: HOBBY TRUCKING INC

GLENN BARTELS PO BOX 413

STEELE, ND 58482

Work: 701-426-9007 Shop: 800-519-2660

Customer P/O: Ifarthing1 000 Orig R/O: 0 Completion Date: 3/26/2018

Unit Number: 50134 Model Year: 2007 Make/Model: Kenworth W900

Type: Kenworth VIN: 1XKWDB9X87R166433 Meter: 1541120 Miles

Engine S/N: MXS54000

Task: 1 HD OIL PROMC HD OIL CHANGE PROMO

80 - PROMOTIONS T/S

90080

Department: 09

Complaint: Perform Pm Service. Change Oil, Oil & Fuel Filter(S), Grease Chassis, And Perform Inspection.

Cause: MOVED TO PROMATIONS PER CHRIS D (JC)
Correction: PERFORMED SERVICE AND INSPECTION

- FRONT AND REAR DRIVE AXLES SLIGHTLY LOW, TOPPED OFF

- STEER SHAFT SLIP IS LOOSE AND WON'T TAKE GREASE
- OIL PAN GASKET LEAKING, LEFT FRONT
- EXHAUST CLAMP #3 LEAKING SLIGHTLY

							Extended
Supp.	Part		Description / Ref Number	U/M	Quantity	Price	Price
		105816EXX	15W40 DELVAC 1300 BULK QTS	EA	40.0		
		FF5319FLG	FILTER	EA	1.0		
		FS1000FLG	FS PAC	EA	1.0		
		LF3566FLG	FILTER	EA	1.0		
		CouponKW	013-KW COUPON		-1.0	\$25.00	(\$25.00)
03	11-024B	1					
		EPA	EPA CHARGE		1.0	\$5.00	\$5.00
			Parts Quote: 209.49				
				Task 1 Subtotals	Parts:		\$0.00
					Labor:		\$0.00
					Task 1 Subtotals		\$0.00

Task: 2 45-010710 PARTS NOT INCLUDED IN SERVICE

Complaint: PARTS NOT INCLUDED IN SERVICE.

Supp.	Part		Description / Ref Number	U/M	Quantity	Price	Extended Price
		103159EXX	SYN-GR/LB	EA	7.0	\$5.35	\$37.45
		72103-3	GREASE FIT 1/4-28 STR	EA	1.0	\$0.34	\$0.34
		ShopSup	MISC SHOP SUPPLIES TS		1.0	\$0.00	\$0.00
				Task 2 Subtotals	Parts:		\$37.79
					Labor:		\$0.00
					Task 2 Subtotals		\$37.79

Task: 3 555-000000 Check and Advise - General Diagostic

Complaint: CHECK AND ADVISE ON

CUSTOMER STATES LAST NIGHT TRUCK WAS SMOKING HEAVY, INSPECT WATER PUMP, AND HEAD GASKET, POSSIBLE INJECTOR, CUSTOMER STATES OIL AND COOLANT LEVELS ARE GOOD, AND STATES THERE IS NO OIL IN COOLANT OR COOLANT IN OIL, POSSIBLE INJECTOR CUT OUT TEST

Department: 09

Department: 09



4020 Miriam Ave. Bismarck, ND 58501

(701) 224-1026

** Reprint **
Invoice: 280850020

Date / Hour: 3/26/2018 10:47:35AM

Repair Order: 243630 Customer: 01784 Branch: Bismarck Total Invoice: \$37,744.29 ***COD***

Page 2 of 7

Department: 09

Bill To: WAYNE TRANSPORTS

COD INVOICES ONLY

FOR DRIVERS OF CUSTOMER ROSEMOUNT, MN 55068

Ship To: HOBBY TRUCKING INC

GLENN BARTELS PO BOX 413

STEELE, ND 58482

Work: 701-426-9007 Shop: 800-519-2660

Customer P/O: Ifarthing1 000 Orig R/O: 0 Completion Date: 3/26/2018

Correction: HOOKED UP AND PERFORMED CUT OUT TEST. NUMBER 4 NOT FIRING. CUSTOMER REQUESTED ALL SIX INJECTORS. REMOVED AND REPLACED ALL INJECTORS. INSTALLED OVERHEAD AND ADJUSTED. INSTALLED VALVE COVERS AND RAN ENGINE. STILL HAS MISS AND STILL SMOKES. NUMBER 4 IS VERY WEAK. LIKELY SCORED CYLINDER AS THERE IS NO COMPRESSION IN COOLING SYSTEM.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	8S9191	BOLT	EA	6.0	\$1.13	\$6.78
	ShopSup	MISC SHOP SUPPLIES TS		1.0	\$89.64	\$89.64
		Tas	k 3 Subtotals	Parts:		\$6.78
				Labor:	\$	1,120.50
				Miscellaneous:		\$89.64
				Task 3 Subtotals	\$	1,216.92

Task: 4 45-000000 ENGINE SYSTEM

Complaint: PERFORM CAT APPROVED INFRAME OVERHAUL WITH A PLATNIUM KIT, TURBO'S, 4 YEAR WARRANTY.

COTRECTION: DRAINED COOLANT AND ENGINE OIL. REMOVED AIR PIPING. DISASSEMBLED HEAD AND REMOVED FROM ENGINE FOUND THAT NUMBER 4 CYLINDER WAS BLOWN ON HEAD GASKET. CHECKED LINER PROJECTION AND FOUND NUMBER 4 AND 5 LOW. REMOVED OIL PAN AND REMOVED OIL PIPING AND STIFFENER PLATE. PULLED PISTON COOLERS. PULLED PACKS OUT OF BLOCK. CLEANED BLOCK AND INSPECTED. FOUND NUMBER BLOCK HAD BEEN CUT ALREADY. NUMBERS 1-4 WERE CUT TO 0.030" NUMBER 5 WAS AT 0.031 AND NUMBER SIX WAS AT 0.032. CHECKED SHIMS AND FOUND THAT THE SIZES AVAILABLE WERE 0.0304" AND 0.0324" HAD MACHINE TECH CUT NUMBER 5 TO MATCH 6 SO THAT LINER PROJECTION WOULD BE EVEN ACROSS THE BOARD. REMOVED AND REPLACED MAIN BEARINGS AND TORQUED MAIN CAPS. INSTALLED NEW PACKS AND INSTALLED NEW ROD BEARINGS. TORQUED ROD CAPS. INSTALLED SPACER PLATE GASKET AND NEW SPACER PLATE AND MEASURED. LINER PROJECTION WAS 0.004 ACROSS THE BOARD. REMOVED SPACER PLATE AND INSTALLED GASKET DRESSING TO SPACER PLATE GASKET. INSTALLED ORINGS WATER GROMMETS SPACER PLATE AND GASKET AND HEAD GASKET. GROOMED NEW HEAD AND INSTALLED ON ENGINE. INSTALLED NEW HEAD BOLTS AND TORQUED. INSTALLED OVERHEAD WITH NEW IVA HOUSINGS. SET OVERHEAD. INSTALLED VALVE COVERS. REMOVED AND REPLACED WATER PUMP. INSTALLED NEW TURBOS. INSTALLED NEW OIL PUMP AND INSTALLED PIPING. WITH STIFFENER PLATE. INSTALLED OIL PAN. FILLED WITH OIL AND REPLACED OIL FILTER. REPLACED FUEL FILTER. FILLED WITH WATER AND RAN ENGINE. DRAINED WATER AND FILLED WATER AND ONE MORE TIME AND DRAINED. FILLED WITH FRESH COOLANT. REPLACED COOLANT FILTER. TOOK TRUCK TO DYNO.

SET UP TOOL TO LAST MACHINEST TOOLING CUT. MEASURED OUT #5 AND SET IT UP FOR 1 SIZE LARGER SHIM. MEASURED FINAL DEPTH AT .032 AROUND THE HOLE SAME AS #6 CYLINDER.

Supp.	Part		Description / Ref Number	U/M	Quantity	Price	Extended Price
		07447	HAND PAD	EA	2.0	\$2.31	\$4.62
		10R9925-C1	KIT-PLATINUM	EA	-1.0	\$5,436.69	(\$5,436.69)
		10R1888-C1	TURBO GP	EA	-1.0	\$1,200.71	(\$1,200.71)
		10R2407-C1	TURBO GP BAS	EA	-1.0	\$700.65	(\$700.65)
		20R0271-C1	ACTUATOR L1 CORE	EA	-2.0	\$207.08	(\$414.16)
		20R0271-C1	ACTUATOR L1 CORE	EA	-1.0	\$207.08	(\$207.08)
		105816EXX	15W40 DELVAC 1300 BULK QTS	EA	44.0	\$3.09	\$135.96
		105FBC	GREASE-MOTOR ASSY 10 OZ L003	EA	1.0	\$5.63	\$5.63
		1090077	SEAL O RING	EA	1.0	\$8.71	\$8.71
		10R1888	TURBO GP	EA	1.0	\$2,311.73	\$2,311.73



4020 Miriam Ave. Bismarck, ND 58501

(701) 224-1026

** **Reprint** **
Invoice: **280850020**

Date / Hour: 3/26/2018 10:47:35AM

Repair Order: 243630 Customer: 01784 Branch: Bismarck Total Invoice: \$37,744.29 ***COD***

Page 3 of 7

Bill To: WAYNE TRANSPORTS

COD INVOICES ONLY

FOR DRIVERS OF CUSTOMER ROSEMOUNT, MN 55068 Ship To: HOBBY TRUCKING INC

GLENN BARTELS PO BOX 413

STEELE, ND 58482

Work: 701-426-9007 Shop: 800-519-2660

Work: 701-426-9007	Shop: 800-519-2	1660					
Customer P/O:	lfarthing1	lfarthing1 000 Orig R			Completion Date: 3/26/2018		
10R1888-C1	TURBO GP		EA	1.0	\$1,200.71	\$1,200.7	
10R2407	TURBO GP BAS		EA	1.0	\$1,791.57	\$1,791.57	
10R2407-C1	TURBO GP BAS		EA	1.0	\$700.65	\$700.65	
10R9925	KIT-PLATINUM		EA	1.0	\$11,525.21	\$11,525.21	
10R9925-C1	KIT-PLATINUM		EA	1.0	\$5,436.69	\$5,436.69	
1135304	SEAL		EA	2.0	\$13.83	\$27.66	
1241854	BOLT		EA	10.0	\$14.88	\$148.80	
1241855	BOLT 12PT		EA	16.0	\$13.52	\$216.32	
1360-4	SLEEVE, 1/4"		EA	1.0	\$0.14	\$0.14	
1986855	TUBE AS		EA	1.0	\$41.80	\$41.80	
20R0271	ACTUATOR AS		EA	2.0	\$799.55	\$1,599.10	
20R0271	ACTUATOR AS		EA	1.0	\$799.55	\$799.55	
20R0271-C1	ACTUATOR L1 CORE		EA	2.0	\$207.08	\$414.16	
20R0271-C1	ACTUATOR L1 CORE		EA	1.0	\$207.08	\$207.08	
2470055	HOSE		EA	1.0	\$41.66	\$41.66	
2470266	HOSE		EA	1.0	\$37.50	\$37.50	
2884210	TOWELS SHOP		EA	2.0	\$8.05	\$16.10	
3196059	KIT-DIAPHRAG		EA	1.0	\$132.77	\$132.77	
3214323	HARNESS AS		EA	1.0	\$160.82	\$160.82	
3214324	HARNESS AS		EA	1.0	\$127.09	\$127.09	
4520PAL	BRAKE CLEAN		EA	4.0	\$2.29	\$9.16	
4589587	PAINT YELLOW		EA	2.0	\$8.41	\$16.82	
5H1504	WASHER		EA	2.0	\$0.99	\$1.98	
614421	PLATE SPACER		EA	1.0	\$408.56	\$408.56	
7204	KEENSERT THN 5/16-18 T	HRD	EA	1.0	\$4.89	\$4.89	
9S8752	NUT		EA	5.0	\$0.17	\$0.85	
9X6458	WASHER HARD		EA	1.0	\$0.43	\$0.43	
B9226-0406TRP	CLAMP-T BOLT SPRING -6	4	EA	1.0	\$3.69	\$3.69	
CT05317	TIE-CABLE 50LB 15.5" BLK		EA	25.0	\$0.14	\$3.50	
CT05512	TIE-CABLE 120LB, 15.25" E	BLK	EA	15.0	\$0.25	\$3.75	
CT300LTRP	TORQUE CLAMP		EA	1.0	\$6.86	\$6.86	
EC3101	COOLANT- CONCENTRAT	E 1 GAL	EA	1.0	\$10.41	\$10.41	
HWU00127	BOLTS		EA	1.0	\$0.09	\$0.09	
HWU05197	NUT, NC NUT- 1/4-20 GR 8	3	EA	1.0	\$0.07	\$0.07	
HWU05223	NUT, NC NUT- 3/8-16 GR 8	3	EA	1.0	\$0.09	\$0.09	
HWU05223	NUT, NC NUT- 3/8-16 GR 8	3	EA	2.0	\$0.09	\$0.18	

^{**} See Last Page for Invoice Total **



4020 Miriam Ave. Bismarck, ND 58501

(701) 224-1026

** Reprint **
Invoice: 280850020

Date / Hour: 3/26/2018 10:47:35AM

Repair Order: 243630 Customer: 01784 Branch: Bismarck Total Invoice: \$37,744.29 ***COD***

Page 4 of 7

Department: 09

Department: 09

Bill To: WAYNE TRANSPORTS

COD INVOICES ONLY

FOR DRIVERS OF CUSTOMER ROSEMOUNT, MN 55068

Ship To: HOBBY TRUCKING INC

GLENN BARTELS

PO BOX 413 STEELE, ND 58482

Work: 701-426-9007 Shop: 800-519-2660

Customer P/O:	lfarthing1 000	Orig	R/O: 0	Completion Date: 3	/26/2018
HWU10129	BOLT-HEX M6-1.00X20 CL10.9 Z	EA	1.0	\$0.16	\$0.16
HWU11621	NUT-HEX SL NYL M6-1.00 CL10	EA	1.0	\$0.08	\$0.08
SG4	SILGLIDE	EA	1.0	\$13.54	\$13.54
SLO 500005285	SHELL ELC 50/50 RED BULK	EA	48.0	\$3.11	\$149.28
WF2073FLG	WF PKG	EA	1.0	\$16.75	\$16.75
CoPaywCAT	4 YEAR UNLIMITED MILE WARRATNY.		1.0	\$1,930.00	\$1,930.00
ShopSup	MISC SHOP SUPPLIES TS		1.0	\$540.00	\$540.00
	Ta	sk 4 Subtotals	Parts	\$	19,783.88
			Core Chg		\$7,959.29
			Core Ret	(\$7,959.29)
			Labor		\$6,750.00
			Miscellaneous		\$2,470.00
			Task 4 Subtotals	\$	29,003.88

Task: 5 41-010003 REPLACE AIR FILTER

Complaint: REPLACE AIR FILTER.

Correction: TWISTED COVERS OFF THE TOP OF AIR FILTERS. REMOVED NUTS OFF CAPS. PULLED CAPS OFF. SLIDE OUT AIR FILTERS. SET CAPS IN PLACE

TORQEUD DOWN NUTS. TWISTED CAPS BACK ON.

Supp.	Part		De	escription / Ref Number		U/M	Quantity	Price	Extended Price
		AF25248FLG	PA	C		EA	2.0	\$74.63	\$149.26
		ShopSup	MI	SC SHOP SUPPLIES TS			1.0	\$16.20	\$16.20
					Task 5 Subtotals		Parts:		\$149.26
							Labor:		\$202.50
							Miscellaneous:		\$16.20
							Task 5 Subtotals		\$367.96

Task: 6 41-040003 INTAKE SYSTEM - INTERCOOLER - REPAIR

Complaint: PRESSURE CHECK AIR TO AIR.

Correction: PRESSURE TESTED CHARGED AIR COOLER AND FOUND BIG CRACK. CUSTOMER APPROVED REPLACEMENT. REMOVED AC CONDENSOR AND

REMOVED CHARGED AIR COOLER. TOOK RADIATOR TO WASH BAY AND WASHED OUT WHILE IT WAS BARE RADIATOR. INSTALLED NEW

CHARGED AIR COOLER. INSTALLED CONDENSOR.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	222066	COOLER, KENWORTH K09364	EA	1.0	\$545.20	\$545.20
	ShopSup	MISC SHOP SUPPLIES TS		1.0	\$10.80	\$10.80
			Task 6 Subtotals	Parts:		\$545.20
				Labor:		\$135.00
				Miscellaneous:		\$10.80
				Task 6 Subtotals		\$691.00

Task: 7 45-000000 ENGINE SYSTEM

Complaint: REPLACE OIL COOLER.

Department: 09



4020 Miriam Ave. Bismarck, ND 58501

(701) 224-1026

** Reprint ** Invoice: 280850020

Date / Hour: 3/26/2018 10:47:35AM

Repair Order: 243630 Customer: 01784 Branch: Bismarck Total Invoice: \$37,744.29 ***COD***

Page 5 of 7

Department: 09

Bill To: WAYNE TRANSPORTS

COD INVOICES ONLY

FOR DRIVERS OF CUSTOMER ROSEMOUNT, MN 55068

Ship To: HOBBY TRUCKING INC

GLENN BARTELS

PO BOX 413

STEELE, ND 58482

Work: 701-426-9007 Shop: 800-519-2660

Orig R/O: 0 Completion Date: 3/26/2018 Customer P/O: Ifarthing1 000 REMOVED OU COOLER AND CLEANED LIP OU FUTER BASE, INSTALLED NEW ORINGS AND NEW OU COOLER

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	10R2112-C1	CORE AS OIL L1 CORE	EA	-1.0	\$271.42	(\$271.42)
	10R2112	CORE AS OIL	EA	1.0	\$855.23	\$855.23
	10R2112-C1	CORE AS OIL L1 CORE	EA	1.0	\$271.42	\$271.42
	ShopSup	MISC SHOP SUPPLIES TS		1.0	\$30.24	\$30.24
		Tas	sk 7 Subtotals	Parts:		\$855.23
				Core Chg:		\$271.42
				Core Ret:		(\$271.42)
				Labor:		\$378.00
				Miscellaneous:		\$30.24
				Task 7 Subtotals	9	1,263.47

CUT BLOCK FOR SLEEVES Task: 45-020002

Complaint: CUT COUNTER BOARS IF NEEDED.

Correction: SET UP TOOL TO LAST MACHINEST TOOLING CUT. MEASURED OUT #5 AND SET IT UP FOR 1 SIZE LARGER SHIM. MEASURED FINAL DEPTH AT

.032 AROUND THE HOLE SAME AS #6 CYLINDER.

								Extended
Supp.	Part		Description / Ref Number		U/M	Quantity	Price	Price
		07447	HAND PAD		EA	1.0	\$2.31	\$2.31
		4520PAL	BRAKE CLEAN		EA	2.0	\$2.29	\$4.58
		614361	INSERT SEAT		EA	4.0	\$62.85	\$251.40
		9Y3368	INSERT LR		EA	2.0	\$62.85	\$125.70
		ShopSup	MISC SHOP SUPPLIES TS			1.0	\$0.00	\$0.00
				Task 8 Subtotals		Parts:		\$383.99
						Labor:		\$0.00
						Task 8 Subtotals		\$383.99

45-810005 **DYNO - BREAK IN** Department: 09 Task: 9

Complaint: PERFORM DYNO BREAK IN. Correction: PERFORMED BREAK IN DYNO

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	70709	COTTER PIN 3/32X1	EA	4.0	\$0.03	\$0.12
	DYNO Sales	DYNO SALES		1.0	\$180.00	\$180.00
	ShopSup	MISC SHOP SUPPLIES TS		1.0	\$21.60	\$21.60
			Task 9 Subtotals	Parts:		\$0.12
				Labor:		\$270.00
				Miscellaneous:		\$201.60
				Task 9 Subtotals		\$471.72

Task: 10 45-000000 **ENGINE SYSTEM** Department: 09

^{**} See Last Page for Invoice Total **



4020 Miriam Ave. Bismarck, ND 58501

(701) 224-1026

** Reprint ** Invoice: 280850020

Date / Hour: 3/26/2018 10:47:35AM

Repair Order: 243630 Customer: 01784 Branch: Bismarck Total Invoice: \$37,744.29 ***COD***

Page 6 of 7

Bill To: WAYNE TRANSPORTS

COD INVOICES ONLY

FOR DRIVERS OF CUSTOMER ROSEMOUNT, MN 55068

Ship To: HOBBY TRUCKING INC

GLENN BARTELS

PO BOX 413

STEELE, ND 58482

Work: 701-426-9007 Shop: 800-519-2660

Customer P/O: Ifarthing1 000 Orig R/O: 0 Completion Date: 3/26/2018

Complaint: CHECK/REPAIR

RESEAL GEAR HOUSING

Correction: PULLED HVAC SYSTEM INTO VACUUM. REMOVED RADIATOR ASSEMBLY. REMOVED OEM COMPONENTS. REMOVED FRONT ENGINE MOUNT.

REMOVED GEAR HOUSING COVER. REMOVED GEARS AND REMOVED PLATE. CLEANED PARTS AND INSPECTED. INSTALLED NEW GASKET AND PLATE ON BLOCK. INSTALLED AND TIMED GEARS. INSTALLED GEAR HOUSING COVER. INSTALLED FRONT ENGINE MOUNT AND OEM COMPONENTS. INSTALLED RADAITOR AND HOOKED UP REPLACED RECEIVER DRYER. PULLED INTO VACUUM AND CHARGED AC.

Extended Quantity Price Description / Ref Number U/M Supp. Part Price 1075769 SEAL ORING EΑ 20 \$5.13 \$10.26 1425867 **SEALGP** 1.0 \$73.94 \$73.94 1559524 SEAL-INTEGRA \$91.12 EΑ 1.0 \$91.12 1669144 GASKET FΑ \$53 10 \$53 10 10 2233505 SFAL-PRESS I FΑ \$11.22 \$11 22 10 4589587 PAINT YELLOW EΑ 1.0 \$8.41 \$8.41 4735-44003-14 **BLADE-FAN** FΑ 10 \$171.41 \$171.41 5515-250 **RADIATOR HOSE SILICONE 2.50"** EΑ 16.0 \$1.00 \$16.00 5515-300 **RADIATOR HOSE SILICONE 3.00"** FΑ 16.0 \$1 17 \$18.72 5P4142 **BOLT** 2.0 \$3.58 EΑ \$1.79 8T9527 **SEAL** EΑ 1.0 \$16.29 \$16.29 9X6458 WASHER HARD \$0.43 EΑ 1.0 \$0.43 GD11350 DRYER, RECEIVER EΑ 1.0 \$23.86 \$23.86 NUT, NC NUT- 5/16-18 GR 8 HWU05210 FΑ 20 \$0.07 \$0.14 HWU05730 WASHER, SAE FLATWASHER- 5/16 EΑ 2.0 \$0.07 \$0.14 HWU05795 WASHER, SAE FLATWASHER- 5/8 EΑ 2.0 \$0.32 \$0.64 K134-356 GASKET-RADIATOR LOWER FΑ 10 \$12.86 \$12.86 VH11600 KIT- O-RING- HVAC SERVICE- R EΑ 1.0 \$2.92 \$2.92 ShopSup MISC SHOP SUPPLIES TS \$172.80 \$172.80 10 Task 10 Subtotals \$515.04 Parts: \$2,160.00 Labor: Miscellaneous: \$172.80 Task 10 Subtotals \$2,847.84

Detail Tax Info:		
Bismarck Tax Exempt		\$0.00
Bismarck Taxable		\$224.57
Burleigh County Exempt		\$0.00
Burleigh County Taxable		\$112.29
ND Sales Tax		\$1,122.86
	Total:	\$1,459.72

Total Parts: \$22,277.29

Total Core Charge: \$8,230.71

Total Core Ret: (\$8,230.71)

Total Labor: \$11,016.00

Total Miscellaneous: \$2,991.28

^{**} See Last Page for Invoice Total **



4020 Miriam Ave. Bismarck, ND 58501

(701) 224-1026

** Reprint **
Invoice: 280850020

Date / Hour: 3/26/2018 10:47:35AM

Repair Order: 243630 Customer: 01784 Branch: Bismarck Total Invoice: \$37,744.29 ***COD***

Page 7 of 7

Bill To: WAYNE TRANSPORTS

COD INVOICES ONLY

FOR DRIVERS OF CUSTOMER ROSEMOUNT, MN 55068

Ship To: HOBBY TRUCKING INC

GLENN BARTELS

PO BOX 413 STEELE, ND 58482

Work: 701-426-9007 Shop: 800-519-2660

Customer P/O: Ifarthing1 000 Orig R/O: 0 Completion Date: 3/26/2018

Invoice Subtotal: \$36,284.57

Total Tax: \$1,459.72

Total Invoice: \$37,744.29

 Payment Method
 Terms
 Due Date

 COD
 Net 10th
 3/26/2018

Remit To:

Wallwork Truck Center Bismarck

P.O. Box 1819

Fargo, ND 58107-1819